

REPL COST	127720	LISTED	DATE				TOTAL VALUE ALL BUILDINGS 10861	
REMEDIATING DATA		COMMERCIAL BUILDING						
UNFINISHED								
FIBERBOARD								
PANELING								
DRYWALL/PLASTER								
C & D FACTOR								
INTERIOR FINISH								
O.F.								
TOTAL	127720							
GRADE	116							
TOTAL	110180							
OVERBUILT								
BUYED AREA								
ENCRACEMENT								
ECONOMIC								
REPLACEMENT COST								
GRADE FACTOR								
TOTAL BASE								
ADD. & PORCHES								
INTERIOR FINISH								
ATTIC								
MASONRY/TI-11								
CB/STUCCO/BRICK VENEER/STONE								
SHINGLE ASPH/ASB/WOOD								
BEVEL/DROP/ALUM/DW								
EXTERIOR WALLS								
SPRINKLER								
HTG/AIR CON.								
DWELLING COMPUTATIONS								
STATE/TILE/METAL								
SHINGLE ASPH/ASB/WOOD								
NO. OF UNITS	1.0							
LIVING ACCOMMODATIONS								
ROOF								
NONE UNFIN.								
ATTIC								
EXTERIOR BETTER								
MODERN KITCHEN								
FLOOR/WALL FURNACE								
WARM AIR F G								
NO HEAT 2ND ONLY								
OTHER FEATURES								
FOUNDATION								
TILE ROOM								
BATHROOM								
STANDARD								
EXTERIOR WALL CODES								
PERIMETER								
EXTERIOR WALLS								

NO.	LOC.	NO.	CONSTRUCTION	SIZE	RATE	GRADE	ERECTED	CONDITION	REPLACEMENT CODE	DEPR.	TRUE VALUE
1	12714	168 d	18-	18	768 d		1993	B-5	127720	20	10217
2	12714	256 d	22-	22			2010		5630	5/20	4280
3	12714	256 d	22-	22			2010		5630	5/20	4280
4	12714	168 d	18-	18			2010		30710	30/10	1272

SUMMARY OF BUILDINGS						
MEMORANDA	CONTEMPORARY	RANCH (R)	CAPE	COLONIAL	CONVENTIONAL	

1
 2
 3
 4
 5
 6
 7
 8
 9
 10
 11
 12
 13
 14
 15

1 FRAME
 5 STUCCO
 9 CONCRETE
 2 BRICK
 6 TILE
 10 ENAM. STL
 3 GLASS
 7 STONE
 8 METAL
 4 CB

DO NOT CONFUSE THE TWO

GRADE DENOTES QUALITY OF CONSTRUCTION: A-EXC.; B-GOOD; C-AVERAGE; D-CHEAP; EVERY CHEAP DEPRECIATION FACTOR REFERS TO THE CONDITION: A-EXC.; B-GOOD; C-AVERAGE; D-CHEAP; EVERY CHEAP

CONDITION: 1-EXCELLENT; 2-GOOD; 3-AVERAGE; 4-FAIR; 5-POOR

TOTAL VALUE ALL BUILDINGS 10861